


FIG. 2








FIG. 3B








FIG. 5A




FIG. 5B 10 60 GPI SERVER RIS INTERNET. -100 COMMUNICATIONS INTERFACE -25 - INPUT 30B -USER 30 -

FIG. 5C





FIG. 5E






FIG. 5G





FIG. 51

FIG. 5H








FIG. 5J



,

FIG. 5K






FIG. 5M




FIG. 5N




FIG. 5P




FIG. 5Q





FIG. 6



7A **FIG. 7A**







FIG. 7B





ON SEPTEMBER 15TH, 1997, THE <u>FDA</u> REQUESTED THAT THE MANUFACTURER OF <u>DEXFENFLURAMINE</u>, THE <u>XYZ</u> CO. VOLUNTARILY REMOVE THE ABOVE DRUG FROM THE MARKET. THE REMOVAL FROM THE MARKET IS BASED ON FINDINGS INDICATING THAT PATIENTS TAKING THIS DRUG DEVELOPED HEART VALVULAR DISEASE, WHICH MAY CAUSE HEART FAILURE AND PUT PATIENTS AT RISK FOR BACTERIAL ENDOCARDITIS. UNFORTUNATELY, SOME PATIENTS WITH HEART FAILURE WHO UNDERWENT SURGICAL CORRECTION OF THE VALVULAR DAMAGE ANYONE ON THE DRUG SHOULD STOP USING DIED. IT AT ONCE, SHOULD SEE A DOCTOR AND SHOULD CONSIDER AN ECHOCARDIOGRAM

- * MORE ON WHAT PRECAUTIONS TO TAKE.
- * APPETITE SUPPRESSANTS. GET MORE INFO
- * FOR DOCTOR'S APPOINTMENT. CLICK HERE
- * FOR ECHOCARDIOGRAM. CLICK HERE
- * FOR INSURANCE INFORMATION. CLICK HERE
 - * IF YOU ARE <u>REGISTERED USER</u> PLEASE CHECK YOUR EMAIL "GPI APPOINTMENT" FOR THE APPOINTMENTS ALREADY SCHEDULED AND INSURANCE APPROVAL OBTAINED OR <u>CLICK HERE</u>
 - * FOR SUPPORT GROUPS CLICK HERE












FIG. 11A




FIG. 11B




FIG. 11C




FIG. 11D




FIG. 11E




FIG. 11F




FIG. 11G




FIG. 11H




FIG. 111




FIG. 11J





FIG. 11K






FIG. 12A




FIG. 12B




FIG. 12C 2170 RETRIEVE FROM USER'S PERSONAL INFORMATION DATABASE "HAZARD ASSOCIATED WITH UNTIMELY TRANSMISSION" ATTACH "HAZARD" TO 2180 ALERT MESSAGE RETRIEVE FROM USER'S PERSONAL INFORMATION DATABASE "INFORM A DOCTOR OF ABNORMAL VALUE 2190 UNTIMELY TRANSMITTED" INFORMATION "INFORM A DOCTOR OF NO ABNORMAL VALUE UNTIMELY TRANSMITTED"? 2200 -YES CONTACT DOCTOR 2210 -SCHEDULE PRIORITY 2220 **APPOINTMENT**




FIG. 12E




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B




FIG. 15A




FIG. 15B




FIG. 16




FIG. 17A




FIG. 17B




FIG. 17C




FIG. 18A




FIG. 18B




FIG. 18C




FIG. 19A




FIG. 19B




FIG. 20A

